
Servicii de revizie/reparatie destinate mentenantei elicopterelor Puma

I.D.: 23083250

Data publicarii	11.10.17	Coduri CPV	50212000-4
-----------------	----------	------------	------------

Pretul estimativ:	51.636.853,00 RON
-------------------	-------------------

Descriere: Reparatie curenta pompa hidraulica
Reparatie capitala (RK) bloc comutatie semnale navigatie
Reparatie verin dreapta A20-23751-1
Reparatie verin stanga A20-23751
Reparatie giroverticala 45400131001
Reparatie curenta BRP: -reparatie amortizori de baleiaj, seriile RO430, RO488, M5195, M 57782; - înlocuire resort masele; - retus protectie bolturi pale principale.
Remediere scurgeri clapeta antiretur
Reparatie servocomanda principala ref 7111-4 (eliminare joc rotule)
Reparatie transmitator 1.1088.ZW
Remediere indicator temperatura exterioara
Remediere scurgeri BRP 330A31003005 la ansamblu manson fuzeta si amortizori de baleiaj
Reparatie (RK) motor TURMO IV (1147, 1255, 1204) (1279, 1230)
Aplicare BS RO.3304 (baliza anticolidiune lampa led)
Inlocuire extingtor capota ref. 111.535.163.12
Reparatie pompa carburant ref. C11BA0101 amd C
Reparatie capitala (RK) bloc KSN 770
Reparatie capitala arbore transmisie spate
Reparatie echipamente instalatie hidraulica tren aterizare
Reparatie suport echipament navigatie mobil
Remediere scurgeri servocomanda spate
Reparatii structurale (plansee cargo, carenaje, capace, traverse)
Reparatie (RK) bloc hidraulic, ref.67-840-41600
Reparatie (RK) BRP, ref 330A31-0030-05
Inlocuire rulment anterior si posterior compresor axial
Reparatie (RK) pompa hidraulica ref. FR65WE02005.175A
Reparatie curenta componente transmisie spate (CTI, CTS, arbori transmisie spate)
Reparatie curenta componente transmisie principala (CTP, palier ventilator)
Reparatie si revitalizare cablaj
Reparatie capitala (RK) indicator ref 4550 SN
Reparatie frana dubla A26-21217-M1
Reparatie releu subtensiune, cu montare
Reparatie insonorizare, capitonaje, mocheta
Reparatie amenajare transport persoane (VIP)
Remediere scurgeri la mansoanele ref. 330A31002911
Reparatie curenta bloc hidraulic PA ref 6784041600
Reparatie indicator tahiturbina
Reparatie pale spate (remediere dezlipiri, retus chituire, vopsire)
Reparatie robinet antigivraj
Reparatie (RK) tahogenerator, ref.545344
Inlocuire extingtor cabina ref. 863520.00
Reparatie demaror reper 1028-1
Reparatie regulator tensiune ref.1326
Reparatie bloc regulator ref. 0.064.63.8590
Aplicare BS 05.82, cutie transmisie spate - CTS, ref. 330A33.0000.05
Aplicare BS 05.82, arbore transmisie oblica ref. 330A34100507
Reparatie (RK) CTP, ref 330A32300003
Remediere scurgeri bloc hidraulic PA 67840416
Reparatie distribuitor hidraulic A7824371
Reparatie (RK) CTS, ref 330A 33.0000.05
Reparatie calculator reper PA 41800252023
Reparatie capitala (RK) bloc ERT 160
Reparatie capitala frana rotor
Reparatie bloc E/R DME 40 ref 18283
Reparatie capitala (RK) bloc ART 2000
Reparatie curenta GTM Turmo
Reparatie capitala (RK) bloc GTX 345
Reparatie capitala (RK) bloc configurare CM 2000
Reparatie roata A20217-40-1
Reparatie verin fata A20-23753
Reparatie ansamblu protectie capota culisanta, sigurantare
Reparatie senzor rupere curea
Reparatie cutie comanda si protectie
Reparatie telefon de bord (comutator defect)
Reparatie regulator tensiune
Reparatie cronometru de bord (blocat)
Reparatie transmitator presiune ulei motor
Aplicare BS 249.72.0100
Reparatie palier ventilator WA 266 (inlocuire curele, rulmenti, reparatie arbore intermediar)
Reparatie micropompa ref. 0.044.74.513.0
Aplicare BS 05.82, arbore transmisie fa?a ref. 330A34100501
Reparatie (RK) servocomanda principala ref. SC7111-4
Reparatie cutie comanda navigatie
Reparatie capitala (RK) rezervor combustibil
Reparatie capitala (RK) indicator ref 3500 SN
Reparatie geamuri incalzite
Reparatie calculator PA (instabil canal giratie)
Reparatie indicator tahorotor - ace decalate
Remediere instalatie anemobarometrica
Reparatie pale principale (remediere dezlipiri, retus chituire, vopsire)
Reparatie curenta CTP 330A323000003 (eliminare scurgeri, retus protectii)
Reparatie bloc demaraj ref. 0.172.05.510.0
Remediere scurgeri CTI 330A34400102/WA112
Reparatie capitala (RK) bloc LISA 200AB
Reparatie jamba principala C22093
Reparatie jamba fata C22092
Remediere scurgeri CTS 330A33000005
Reparatie (RK) motor TURMO IV cu asigurare resursa intre RK discuri (1147, 1255, 1204) (1279, 1230)
Reparatie supapa micropompa
Reparatie distribuitor combustibil bloc demaraj
Aplicare BS 05.82, arbore transmisie spate ref. 330A34100514
Revizie tip P2 standard Puma
Reparatie servocomanda spate ref. 7117-1C
