
REPARATII POMPE

I.D.: 100240203

Data publicarii	16.07.24	Coduri CPV	50511000-0
-----------------	----------	------------	------------

Pretul estimativ: 3.305,00 RON - 3.305,00 RON

Descriere: REPARATII POMPA FLYGT 1.7 KW: rebobinare ; lucrari mecanice conexe; inlocuire rulmenti ; ulei REPARATII POMPA WILO 4 KW : inlocuire rulment; inlocuire kit etansare EMU PUMP 35MM VITON; lucrari mecanice conexe ; uscare bobinaj ; refacut legaturi ;
