
Reparat pompe ape uzate Wilo

I.D.: 42611247

Data publicarii	23.04.19	Coduri CPV	50511000-0
-----------------	----------	------------	------------

Pretul estimativ: 56.815,30 RON - 56.815,30 RON

Descriere: Reparata pompa 1 - model Wilo FA 08.73W+FK202-2/22, constand din: - rebobinat stator, - schimbat setul de etansari mecanice, - schimbat setul de rulmenti, - schimbat turbina, - rectificat ax, - schimbat ulei motor si ulei din camera de etansare. Reparata pompa 2 - model Wilo FA 08.73W+FK202-2/22, constand din: - rebobinat stator, - schimbat setul de etansari mecanice, - schimbat setul de rulmenti, - schimbat turbina, - rectificat ax, - schimbat corp pompa, - schimbat ulei motor si ulei din camera de etansare
