
Reparatie si inlocuire senzor de flux

I.D.: 36353567

Data publicarii	04.06.19	Coduri CPV	50421000-2
-----------------	----------	------------	------------

Pretul estimativ:	2.200,00 RON - 2.200,00 RON
-------------------	-----------------------------

Descriere:	Reparatie si inlocuire senzor de flux admisie oxigen, calibrare, efectuare teste de siguranta pentru ventilator PB980.
------------	--
