

## **Pachet reparatii copiatoare**

I.D.: 58866155

---

Data publicarii	14.07.21	Coduri CPV	30125000-1
-----------------	----------	------------	------------

---

Pretul estimativ: 2.000,00 RON - 2.000,00 RON

---

Descriere: Reparatie Lexmark X860 : inlocuire pressure roller, fusser roller, lampa, termistori Reparatie Lexmark W850: inlocuire role preluare, heater roller

---