
Reparatii la sonda izocinetica

I.D.: 44527101

Data publicarii	12.11.19	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ: 5.370,00 RON - 5.370,00 RON

Descriere: Reparatii la sonda izocinetica - Reparatie tub Pitot - 2.040 RON - Reparatie termocuplu - 1.380 RON - Refacere circuite interne si conexiuni electrice - 1.950 RON
