
Reparatie autoclav vertical AES-75 Raypa - garnitura etansare capac

I.D.: 100288177

Data publicarii	18.07.24	Coduri CPV	50421000-2 34913000-0
-----------------	----------	------------	-----------------------

Pretul estimativ: 6.350,00 RON - 6.350,00 RON

Descriere: Reparatie autoclav vertical AES-75 Raypa - garnitura etansare capac; Reparatie centrifuga de laborator Medifuge Thermo seria 42292815 - inlocuire switch, inlocuire arc, reglat mecanism - 2260 lei 2. Reparatie centrifuga de laborator Medifuge Thermo seria 42940105- inlocuire rulmenti, verificari - 2410 lei PREZENTA TINE LOC DE COMANDA
