

Reparatie auto

I.D.: 64787890

Data publicarii	28.12.21	Coduri CPV	34640000-5
-----------------	----------	------------	------------

Pretul estimativ: 3.812,68 RON - 3.812,68 RON

Descriere: 1. BUJIE INCANDESCENTA / BOSCH / 2 90542151 SIGURANTA 15 3 VERIFICARE GENERALA 4 RECONDITIONAT TURBINA 5 FACTURA 21771 / 29.11.2021 6 Garnitura, galerie evacuare / 7 GARNITURA CAPAC CULBUTORI / PAYEN / JM7054 8 Garnitura conducta retur ulei turbo,OE, / R 9 FILTRU ULEI / MANN-FILTER / W753 10 TAXA MEDIU ULEI 11 ULEI TOP TEC 4600 5W30 / LIQUI MOLY / 3759 12 Diagnoza management motor 13 Inlocuirea tuturor bujiilor incandescente 14 Demontare/remontare turbocompresor 15 Demontare/montare capac de chiulasa fata 16 Efectuare test baterie inalta tensiune 17 Inlocuire acumulator 18 Incarcare baterie cu o statie de incarcare 19 00502161 COL.PLAST.NEG.4.8*360 / IMPORT / 00502161 20 Ulei TOP TEC ATF 1800 1L / LIQUI MOLY / 20461 21 FURTUN COMBUSTIBIL 8 / FLENOR / FBS80A 22 Colier furtun 12-20 / BERNER / 303283-25 23 filtru combustibil / BOSCH / F026403006 24 Garnitura chiulasa / FEBI / 105921 25 Antigel / HEPU / P999G12 26 SENZOR UNGHI VOLAN POZ.5 / FEBI BILSTEIN / 33537 27 dr chiulasa si dezechipat echipat
