
Reparatie auto Skoda Octavia BH 10 CPI

I.D.: 98339466

Data publicarii	04.06.24	Coduri CPV	34300000-0
-----------------	----------	------------	------------

Pretul estimativ: 2.000,00 RON - 2.000,00 RON

Descriere: Reparatie auto Skoda Octavia BH 10 CPI: *Inlocuire senzor ax came -senzor ax came -1 buc - 3 ore *D/R furtun intercooler - garnitura intercooler - 1 buc - 2 ore *Inlocuire ulei+filtre - tampon esapament - 2 buc - 2 ore - filtru ulei - 1 buc - filtru aer - 1 buc - filtru combustibil - 1 buc - filtru polen - 1 buc - ulei motor - 5 buc
