
Diverse servicii de intretinere si de reparare

I.D.: 66382363

Data publicarii	14.02.22	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ: 620,00 RON - 620,00 RON

Descriere: Inverter TELWIN 236HD Serie 60974-1 - cleste ESAB MP200 = 1 x 55 lei/buc - stecher = 1 x 10 lei/buc - curatat si uns ventilatoare, inlocuit stecher si cleste masa = 95 lei/buc - Polizor Bosch GWS 20-230H Cod 3601H50L01 Serie 611001760 - perii carbuni =1 x 45 lei/buc - bucsa bronz = 1 x 15 lei/buc - rulment pinion mare 6203 = 1 x 25 lei/buc - vaselina VP729 = 2 x 15 lei/buc - saiba disc = 1 x 25 lei/buc - piulita disc = 1 x 30 lei/buc - cheie disc =1 x 25 lei/buc - inlocuit carbuni, vaselina, cablu alimentare rupt = 1 x 100 lei/buc Demaror generator = 1 x 165 lei/buc
