

---

## SERVICII REPARATII/INTRETINERE TOYOTA LC150 BH22KZZ

I.D.: 59340975

---

Data publicarii	28.07.21	Coduri CPV	50110000-9
-----------------	----------	------------	------------

---

Pretul estimativ: 2.016,85 RON - 2.016,85 RON

---

Descriere: Tip autovehicul TOYOTA LC150 Serie sasiu JTEBH3FJX0K168182 Nr. inmatriculare BH22KZZ Nr. km. 179744 Tip motor An fabricatie 2015 MANOPERA Fara TVA: 650.00 RON Cu TVA: 773.50 RON MATERIALE Fara TVA: 1,366.85 RON Cu TVA: 1,626.55 RON Valoare fara TVA: 2,016.85 RON Valoare TVA: 383.20 RON TOTAL CU TVA: 2,400.05 RON Detalieri deviz: 136075  
Detalieri manopera Nr. Denumire Mecanic Norma Cantitate Tarif Total Norma Val. fara TVA Val. cu TVA 1 REVIZIE 180000 KM 121 4.00 1.00 130.00 4.00 520.00 1138.80 2 RESCRIERE SENZORI PRESIUNE ROTI 121 1.00 1.00 130.00 1.00 130.00 284.70 Detalieri piese Nr. Cod Articol Denumire Cantitate Pret piesa Val. fara TVA Val. cu TVA 1 90915-YZZJ3 FILTRU ULEI 1.00 61.50 61.50 73.19 2 90080-43037 GARNITURA 1.00 6.95 6.95 8.27 3 08880-83853 ULEI MOTOR 5W30 PFE 7.00 61.75 432.25 514.38 4 17801-30080 FILTRU AER 1.00 185.06 185.06 220.22 5 23390-YZZAB FILTRU COMBUSTIBIL 1.00 167.23 167.23 199.00 6 87139-YZZ16 FILTRU POLEN 1.00 88.05 88.05 104.78 7 08823-80

---