
Reparatie videoureteroscop flexibil flex X C

I.D.: 94373481

Data
publicarii 07.03.24

Coduri CPV 50422000-9

Pretul
estimativ: 23.237,00 RON - 23.237,00 RON

Descriere: Reparatie videoureteroscop flexibil flex X C V2 DEFECTIUNI CONSTATATE canal de lucru perforat, neetanseitate OPERATIUNI EXECUTATE dezasamblare videoureteroscop flexibil, inlocuire canal de lucru, inlocuire manson distal de cauciuc, inlocuire manson metalic, reglare sistem control angulare, verificare senzor optoelectronic, refacut etansare lentila frontala, verificare trasee optice.
