
Reparatie motopompa Honda WB 20XT

I.D.: 48140763

| | | | |
|-----------------|----------|------------|------------|
| Data publicarii | 13.07.20 | Coduri CPV | 50800000-3 |
|-----------------|----------|------------|------------|

| | |
|-------------------|-------------------------|
| Pretul estimativ: | 159,66 RON - 159,66 RON |
|-------------------|-------------------------|

| | |
|------------|---|
| Descriere: | Reparatie motopompa Honda WB 20XT -snur demaror -etansare mecanica -ulei -silicon - consumabile -o-ring corp pompa. |
|------------|---|
