
Reparatie microbuz Mercedes Benz Sprinter A-10481

I.D.: 53598103

Data publicarii	22.01.21	Coduri CPV	50112000-3
-----------------	----------	------------	------------

Pretul estimativ: 3.468,57 RON - 3.468,57 RON

Descriere: Reparatie microbuz Mercedes Benz Sprinter A-10481: CONDUCTA ADITIV, DUZA INJECTIE ADITIV, COLIER, GARNITURA INJECTOR SCR, ADBLUE 10L, INLOCUIRE CONDUCTA ADBLUE, INLOCUIRE INJECTOR ADBLUE, TEST DASS, CONSTATARE
