
Servicii de reparare a automobilelor

I.D.: 86713767

Data publicarii	05.09.23	Coduri CPV	50112100-4
-----------------	----------	------------	------------

Pretul estimativ: 911,14 RON - 911,14 RON

Descriere: MATERIALE: SURUB M5X20 - 2 X 0.42 RON + TVA SURUB CAP IMBUS M8X20 - 1 X 0.67 RON + TVA PIULITA M5 - 2 X 0.08 RON + TVA SURUB M5X40 - 2 X 0.24 RON + TVA SURUB M8X30 - 2 X 0.84 RON + TVA SAIBA FI8 - 2 X 0.16 RON + TVA SAIBA FI12 - 2 X 0.21 RON + TVA SENZOR TURATIE ROATA SPATE STG. - 1 X 152.94 RON + TVA COLIER PLASTIC NEGRU 4.7X285 - 10 X 0.42 RON + TVA SENZOR TURATIE ROATA SPATE DR. 1 X 157.98 + TVA MANOPERA: SPALAT AUTO - 1 X 85 RON + TVA DIAGNOSTICARE - 1 X 120 RON + TVA INLOCUIT SENZOR ABS AXA SPATE STG + DR - 2 X 100 RON + TVA REPARAT USA CULISANTA - 2 X 100 RON + TVA
