
Reparatie pompa SL1.50.65.30 COD 98707161

I.D.: 85811192

Data publicarii	09.08.23	Coduri CPV	50511000-0
-----------------	----------	------------	------------

Pretul estimativ: 7.803,76 RON - 7.803,76 RON

Descriere: Lucrari de reparatie pentru electropompa Grundfos tip SL1.50.65.30 care includ: manopera de demontare, constatare defecte si inlocuire piese: rebobinat stator, kit priza stator 1buc., kit cablu 1buc., kit lagare 1buc., kit etansare 1buc., kit garnituri 1buc., ulei ondina
