
Reparat POMPA FLIGHT1.2KW/3000T

I.D.: 48395809

Data publicarii 23.07.20

Coduri CPV

50511000-0

Pretul estimativ: 1.680,00 RON - 1.680,00 RON

Descriere: demontat montat, rebobinat stator, inlocuit rulmenti SKF, inlocuit etansare mecanica, ulei,diverse
