
Reparatie pompa tip LP 10125

I.D.: 92050759

Data
publicarii 15.01.24

Coduri CPV 50511000-0

Pretul
estimativ: 2.711,15 RON - 2.711,15 RON

Descriere: Lucrari de reparatie electropompa LP 10125, care includ: includ constare, manopera si
inlocuire piese kit etansare mecanica 1buc., kit lagar motor 1buc., kit palier motor inf 1buc.
