
Interventie service , constatate si reparare sistem HPLC PERKIN ELMER (afiseaza eroare 993 si 984)

I.D.: 17827300

Data publicarii	20.02.17	Coduri CPV	50400000-9
-----------------	----------	------------	------------

Termenul limita pentru depunere:	21.02.17	Pretul estimativ:	1.500,00 RON
----------------------------------	----------	-------------------	--------------

Descriere:	Interventie service, constatate si reparare sistem HPLC PERKIN ELMER (afiseaza eroare 993 si 984)
------------	---
