
Servicii de reparare masina de spalat Electrolux

I.D.: 50053085

Data publicarii	25.09.20	Coduri CPV	50532000-3
-----------------	----------	------------	------------

Pretul estimativ: 287,88 RON - 287,88 RON

Descriere: Servicii de reparare masina de spalat Electrolux Verificarea ansamblului, inlocuit sistem inchidere hublou, inlocuit pompa evacuare,reglat presostat, reparat placa programator cu inlocuire de piese, probe functionale. Tarif = 203,00 Material = 84,88 Total = 287.88
