
Servicii de reparatie uscator de rufe - HEINER

I.D.: 61289736

Data publicarii	23.09.21	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ:	325,20 RON - 325,20 RON
-------------------	-------------------------

Descriere:	Servicii de reparatie uscator de rufe HEINER: - servicii de constatare si manopera inlocuire curea - 1 buc
------------	--
