
reparat POMPA FLIGHT1.2KW/3000T

I.D.: 53931218

Data publicarii 03.02.21

Coduri CPV

50511000-0

Pretul estimativ: 5.430,00 RON - 5.430,00 RON

Descriere: demontat montat, rebobinat stator, inlocuit rulmenti SKF, inlocuit etansare mecanica, ulei,diverse
