
Servicii reparat Pompa Flight 1,2 KW/3000T

I.D.: 45981854

Data publicarii 29.04.20

Coduri CPV

50511000-0

Pretul
estimativ: 1.332,00 RON - 1.332,00 RON

Descriere: Demontat montat, rebobinat stator, inlocuit rulmenti SKF, inlocuit etansare mecanica, ulei,diverse
