

---

## **Servicii de reparatie gunoiera Mercedes-Benz Econic DB12SCP conform deviz din 04/2019**

I.D.: 43150243

---

Data publicarii	13.06.19	Coduri CPV	50100000-6
-----------------	----------	------------	------------

---

Pretul estimativ: 22.605,00 RON - 22.605,00 RON

---

Descriere: Manopera inlocuit calculator c.v. Allison MD3060 Manopera inlocuit modul comanda centrala agregate (pompa, lifturi si capac) Inlocuit rulment stg fata citator de ABS Refacut instalatie electrica senzori ultrasonici de proximitate Refacut instalatie sensor lift cabina Inlocuit sensor lift cabina Reprogramare + recalibrare calculator Allison MD3060 Reprogramare + recalibrare modul comanda centrala agregate (pompa, lifturi si capac) Manopera inlocuit ulei c.v.a Calculator cutie de viteze automata Allison MD3060 Modul comanda centrala agregate (pompa, lifturi si capac) SH Rulment roata cu cititor ABS Senzor lift cabina Kit filtre ulei Allison MD3060 Ulei

---