
Reparatie pompa Wilo Helix First V 1612

I.D.: 92809561

Data publicarii	29.01.24	Coduri CPV	50510000-3
-----------------	----------	------------	------------

Pretul estimativ: 9.360,80 RON - 9.360,80 RON

Descriere: Reparatie pompa Wilo Helix First V 1612 (art 4201007/19w21/777643), constand din: - schimbarea setului de rulmenti (motor+cuplaj), - schimbarea cartusului de etansare, - schimbare etaj pompare 13.2 - 2 bucati, - manopera aferenta.
