

## Pachet piese MARUYAMA BC5020H-RS

I.D.: 58558167

---

Data publicarii	01.07.21	Coduri CPV	16810000-6
-----------------	----------	------------	------------

---

Pretul estimativ: 2.093,23 RON - 2.093,23 RON

---

Descriere: Reparatie motocoasa Maruyama cu urmatoarele piese: pompa sprit 2T (Walbro:188512,180570\_MTD700-790:791-683974,791-181558,SG-2044600\_ikra XL) !nf>59-070 B14698 BUC 3 distantier cutit Maruyama BC 4320/5020 -01 #nou 10 mm, de la sol-palpator 230849 BUC 3 filtru combustibil, stut D3.8/4.8 mm (HQ 503 44 32-01) RP 170-180 BUC 3 disc/cutit\_Y 3T D255 Ø25.4 =3.0mm 'German' pt.Maruyama,Stihl:FS65/66/74/96(41120071004,41127134100) 6-001 BUC 3 lama taiere fir nylon Maruyama BC...,MX... N°38 !nf> 231882 230747 BUC 1 extensie aparatoare cap damil Maruyama BC 2300/320/4320/5020, MX 21/24/27/33 230748 BUC 1 aparatoare cap damil Maruyama BC 4320/5020, incl.231262&223180&221580&232093&231704&223179&220632 232092 BUC 3 demaror Maruyama BCV 5020 | NE500/39 287918 BUC 3 carburator Maruyama BC 4320/5020 (284109) 279890 BUC 1 carburator Maruyama BCV 5020 :NE500/39 |4.1| 289725 BUC 1 membrana carburator Maruyama MX 21/24/27, BC 2300 #pompare 283905 BUC 3 garnitura carburator Maruyama BC/BCV 4320/5020 @membrana pomp. 263727 BUC 3 membrana carburator Maruyama MX 21/24/27/33, BC 320/2300 #alimentare 262994 BUC 3 garnitura carburator Maruyama MX 21/24/27,BC 2300 @membrana alim. 282576 BUC 3 cap damil Maruyama BC 320,500,4320/5020 227409 BUC 3 lama taiere fir nylon Maruyama BC...,MX...: 230747cu surub261250+piulita228325 231882 SET 1 TRANSPORT INTERN. T BUC 1

---