

Reparare Invertor sudura Telwin TECHNOLOGY 236 HD

I.D.: 61284538

Data publicarii	24.09.21	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ: 655,14 RON - 655,14 RON

Descriere: Invertor sudura Telwin TECHNOLOGY 236 HD 1 KIT IGBT+ Doide 981293 1,00 Buc 225,00 2 Mufa mama DX 25 712417 712035 2,00 Buc / 12,60 total 25,20 3 Mufa tata DX25 - 1 buc 712414 712039 2,00 Buc / 12,60 total 25,20 4 Cleste de masa TOLEDO 300A 712231 1,00 Buc 16,80 5 BACK PANEL 322694 1,00 Buc 34,50 6 Panou frontal Technology 236HD 321039 1,00 Buc 34,50 7 Cablu sudura 25mm CABLU SUDURA25 3,00 Buc / 20,16 total 60,48 8 Rezistor 112048 1,00 Buc 5,00 9 Demontat/montat tranzistoare IGBT S315 1,00 UM 145,50 10 Demontat/montat cleste sudura S293 1,00 UM 10,20 11 Demontat/montat borne baterii acumulate Demontat/montat borne aparate sudura S881 1,00 UM 36,38 12 Demontat/montat capac frontal Demontat/montat capac frontal+spate S171 1,00 UM 36,38 TOTAL FARA TVA (RON) 655,14 lei
