

SERVICII VULCANIZARE AUTOVEHICULE

I.D.: 63476740

Data publicarii 23.11.21 Coduri CPV 50116500-6

Pretul estimativ: 17.404,00 RON - 17.404,00 RON

Descriere: Demontat/montat anvelope, schimb roti fata pentru autov :-Tractor BC 02 UAT;-Autoutil Iveco BC 16 APL;-Tractor U650 BC 25 APL;-Buldoexcavator TEREX MOINESTI BC-006;-Remorca BC030 Moinesti;-Remorca BC23 APL;Buldoexcavatorll. Demontat/montat anvelope, schimb roti spate pentru auto :Tractor BC02UAT;-Autoutilitara Iveco BC16APL;-Tractor U650BC25 APL;-Buldoexcavator TEREX MOINESTI - BC006;-Remorca BC 030 Moinesti;-Remorca BC 23 APL;Buldoexcavatorll. ,demontat/montat roata/echilibrat roata/100g plumb pentru BC16APL, demontat/montat roata fata, dejantat/jantat, montat valva janta pentr BC02UAT, BC25APL, demontat/montat roata fata, Dejantat/jantat, montat valva camera pentru Buldoexcavator TEREX MOINESTI - BC-006+Buldoexcavatorll., demontat/montat roata spate, dejantat/jantat, montat valva janta pentr BC02UAT, BC25APL, demontat/montat roata spate, dejantat/jantat, montat valva camera pentru Buldoexcavator TEREX MOINESTI- BC-006+Buldoexcavatorll., Demontat/montat roata fata, dejantat/jantat roata+petic pentru BC02UAT, BC25APL, Demontat/montat roata fata, dejantat/jantat roata+petic pentru Buldoexcavator TEREX MOINESTI-BC-006+Buldoexcavatorll, Demontat/montat roata fata,dejantat/jantat roata+petic pentru BC16APL, Demontat/montat roata spate, dejantat/jantat roata+petic pentru BC02UAT, BC25APL, Demontat/montat roata spate, dejantat/jantat roata+petic pentru Buldoexcavator TEREX MOINESTI - BC-006+Buldoexcavatorll, demontat/montat roata spate,dejantat/jantat roata+petic ptBC16APL