
Reparatie pompa SP 8A-10

I.D.: 100561716

Data publicarii	23.07.24	Coduri CPV	50511000-0
-----------------	----------	------------	------------

Pretul estimativ: 3.284,00 RON - 3.284,00 RON

Descriere: Lucrari de reparatie pompa Grundfos SP 81-10, care includ: demontare pompa, constatare si inlocuire : 1 buc. kit bulk rotor, 1 buc kit ax si manopera aferenta.
