
Servicii de reparare masina de spalat Hotpoint Ariston

I.D.: 87269102

Data publicarii	21.09.23	Coduri CPV	50532000-3
-----------------	----------	------------	------------

Pretul estimativ: 500,00 RON - 500,00 RON

Descriere: Reparatie masina de spalat rufe Hotpoint Ariston ; inlocuit pompa evacuare apa , arc sustinere cuva ,reparat modul electronic la DGASPC SECTOR 1 / CARPAD Stejarel
