
Reparatie VW TRANSPORTER

I.D.: 53509851

Data publicarii	20.01.21	Coduri CPV	50112000-3 50110000-9
-----------------	----------	------------	-----------------------

Pretul estimativ:	253,49 RON - 253,49 RON
-------------------	-------------------------

Descriere:	Inlocuit senzor ABS stanga spate .(devizul contine piese, consumabile si manopera aferenta inlocuirii pieselor)
------------	--
