
servicii de reparatie biomicroscop si fundus camera

I.D.: 56775498

Data publicarii	06.05.21	Coduri CPV	50400000-9 50421000-2
-----------------	----------	------------	-----------------------

Pretul estimativ: 4.305,00 RON - 4.305,00 RON

Descriere: 1) Reparatie Fundus Camera (model AFC-30): Constatate, Demontare, Reparatie, Montare, Calibrare, Verificare 2) Verificare tehnica biomicroscop (model SL-1600 si SL-250): Verificare, Constatate 3) Piese schimb biomicroscop: bec halogen 6V - 1 bucata, sursa biomicroscop - 1 bucata; Bec halogen 6 V - 369 lei fara TVA; sursa biomicroscop - 1.230 lei fara TVA; Reparatia si verificarea tehnica a celor doua biomicroscope si a unui fundus camera - 2.706 lei fara TVA. Garantie piese si reparatie minim 6 luni.
