

SERVICII REPARATII/INTRETINERE TOYOTA HILUX BH11TBX

I.D.: 42382603

Data publicarii 04.04.19 Coduri CPV 50110000-9

Pretul estimativ: 4.156,36 RON - 4.156,36 RON

Descriere: Tip autovehicul TOYOTA HILUX Serie sasiu AHTFR22G306018644 Nr. inmatriculare BH11TBX Nr. km. 184421 Tip motor An fabricatie 2009 MANOPERA Fara TVA: 1,170.00 RON Cu TVA: 1,392.30 RON MATERIALE Fara TVA: 2,986.36 RON Cu TVA: 3,553.77 RON Valoare fara TVA: 4,156.36 RON Valoare TVA: 789.71 RON TOTAL CU TVA: 4,946.07 RON Detaliere deviz: 102473 Detaliere manopera Nr. Denumire Mecanic Norma Cantitate Tarif Total Norma Val. fara TVA Val. cu TVA 1 REVIZIE COMPLETA 121 4.00 1.00 130.00 4.00 520.00 1138.80 2 INLOCUIT TRAPEZ STG FATA 121 4.00 1.00 130.00 4.00 520.00 1138.80 3 VERIFICAT DIRECTIE 121 1.00 1.00 130.00 1.00 130.00 284.70 Detaliere piese Nr. Cod Articol Denumire Cantitate Pret piesa Val. fara TVA Val. cu TVA 1 90915-YZZJ3 FILTRU ULEI 1.00 55.92 55.92 66.54 2 90080-43037 GARNITURA 1.00 6.23 6.23 7.41 3 08880-80840 ULEI SINT MOT 5W30 208L 7.10 44.16 313.54 373.11 4 08885-80606 ULEI SINT TRAN 75W90 1L 2.00 76.03 152.06 180.95 5 08885-81004 ULEI DIFFERENTIAL 85W90 20L 3.50 37.27 130.45 155.23 6 17801-0C020 FILTRU AER 1.00 194.65 194.65 231.63 7 23390-YZZA2 FILTRU COMBUSTIBIL 1.00 92.14 92.14 109.65 8 87139-YZZ16 FILTRU POLEN 1.00 83.28 83.28 99.10 9 08823-80004 LICHID FRANA DOT 5.1 1L 1.00 69.34 69.34 82.51 10 90430-24003 GARNITURA ETANSARE 1.00 5.80 5.80 6.90 11 LM3552 VASELINA CARDAN 1.00 25.21 25.21 30.00 12 48069-0K040 TREPEZ INFERIOR STG 1.00 1561.27 1561.27 1857.91 13 48190-0K010 SURUB 1.00 78.96 78.96 93.96 14 48190-0K030 SURUB 1.00 98.88 98.88 117.67 15 48198-0K010 SAIBA