
Reparatie panouri solare

I.D.: 103018763

Data publicarii	17.09.24	Coduri CPV	50721000-5
-----------------	----------	------------	------------

Pretul estimativ: 23.687,20 RON - 23.687,20 RON

Descriere: Serviciul de reparare panouri solare cuprinde : a. Montare aerisitor solar -6 buc b. Completare antigel Tifocor - 80 litri c. Solutie curatare Cleanex Solar Plus - 10 litri d. Inlocuire racord tub flexibil - 5 buc e. Inlocuire senzor boiler - 1 buc f. Inlocuire tuburi vidate - 20 buc.
