
REPARATII POMPA JUNG ,WILO

I.D.: 93133397

Data
publicarii 09.02.24

Coduri CPV

50500000-0

Pretul
estimativ: 4.013,00 RON - 4.013,00 RON

Descriere: REPARATII POMPA WILO 2.2 KW :rebobinare ; inlocuire rulmenti ;inlocuire presutupa;lucrari
mecanice conexe ; REPARATII POMPA JUNG 3.7 KW UAK 35/2 BN2: rebobinare ; lucrari
mecanice conexe ; inlocuire rulmenti ; ulei ; semeringuri; bucsat cota rulment ; echilibrare
dinamica
