
piese si service la auto SB02DPL

I.D.: 48671875

Data publicarii	05.08.20	Coduri CPV	34320000-6
-----------------	----------	------------	------------

Pretul estimativ:	306,37 RON - 306,37 RON
-------------------	-------------------------

Descriere: Inlocuit releu ventilator racire Diagnoza Verificat instalatie electrica motor (bec 12v 5w
1*7,98 releu 40a 1*130,33 manpera 168,06 lei
