

Reparatie camera frigorifica-1 buc

I.D.: 82331772

| | | | |
|-----------------|----------|------------|------------|
| Data publicarii | 18.05.23 | Coduri CPV | 50800000-3 |
|-----------------|----------|------------|------------|

Pretul estimativ: 4.915,85 RON - 4.915,85 RON

Descriere: Azot tehnic=3buc*202.80=608.41 lei; Ulei SEZ32=2LITRI*146.44=292.89 LEI; Racord flexibil 22mm=1buc*129.21=129.21 lei; Teava Cu 22x1mm(frigoirifica)=2ml.*125.63=251.25; Cot Cu 22x90=4buc*5.60=22.40 lei; Oxigen=1buc*200.20=200.20; Electrizi Ag=0.30Kg*249.99=75.00 lei; Freon R404=4kg*196.63=786.50 lei; Constatore pierdere freon cu presa de azot si spuma de sapun=8ore*85.00=680 lei; Inlocuit ulei compresor Bizer-sermiermetic 2EC-3.2Y=4ore*85.00=510.00 lei; Inlocuit racord flexibil fi 22mm si tronson de teava Cu22=6*85.00=425.00 lei; Verificat etansietate instalatie in urma reparatiei cu presa de azot=3*85.00=255,00 lei; Vacuumat instalatia si completat cu freon R404, pus instalatia in functiune=8ore*85.00=680.00 lei
