

---

## reparatii toyota hilux

I.D.: 104864488

---

Data  
publicarii 30.10.24

Coduri CPV 50112100-4

---

Pretul  
estimativ: 33.382,23 RON - 33.382,23 RON

---

Descriere: Oferta neacceptata in termen: inlocuire garnitura capac culbutori,demontat-remontat radiator,inlocuit senzor abs,reparat caroserie +vopsit

---