

---

## **REPARATII POMPE FLYGT +MIXER FLYGT**

I.D.: 56278605

---

Data publicarii	19.04.21	Coduri CPV	50511000-0
-----------------	----------	------------	------------

---

Pretul estimativ: 2.486,00 RON - 2.486,00 RON

---

Descriere: Reparatii pompa Flygt 2.4 kw:rebobinat ; lucrari mecanice conexe ; schimbat rulmenti ;inlocuit semering ; presutupa;ulei; -Reparatii pompe Flygt 2.4 kw: rebobinat; lucrari mecanice conexe; schimbat rulmenti ; inlocuit semering ; presutupa; ulei; -Reparatii mixer Flygt 2.4 kw; rebobinat ; inlocuire rulmenti ; presutupa ; lucrari mecanice conexe

---