
Reparatie Skoda Rapid

I.D.: 65500126

Data publicarii	17.01.22	Coduri CPV	50112100-4
-----------------	----------	------------	------------

Pretul estimativ:	1.104,77 RON - 1.104,77 RON
-------------------	-----------------------------

Descriere: Inspectie service fără schimb ulei Service lichid frână - efectuat Sistem ambreiaj aerisit Eficacitate frânare - verificat Set lamele stergator fata - inlocuit Placute frana fata inlocuit
