

Reparatie auto Mercedes Sprinter Trituro

I.D.: 67513542

| | | | |
|-----------------|----------|------------|------------|
| Data publicarii | 25.03.22 | Coduri CPV | 50112000-3 |
|-----------------|----------|------------|------------|

Pretul estimativ: 3.093,27 RON - 3.093,27 RON

Descriere: Cruce cardan 6144980013 : 1 bc X 113.45 = 113.45 Cruce cardan G11077PC : 1 bc X 90.76 = 90.76 Cruce cardan G15073PC : 1 bc X 104.2 = 104.20 Ulei transmisie ATF Premium VI : 2 l X 52.94 = 105.88 Rulment 2996025 : 1 bc X 172.27 = 172.27 Rulment 101017 : 1 bc X 234.45 = 234.45 Rulment VKBA3584 : 1 bc X 208.40 = 208.40 Tub flexibil esapament A.Z. Meistererteile : 1 bc X 89.08 = 89.08 Demontat/ Montat Ax cardanic : 3 h X 126.05 = 378.15 Inlocuit cruci cardan : 1.5 h X 126.05 = 189.07 Echilibrat ax cardanic : 2 h X 126.05 = 252.10 Demontat/ Montat grup transmisie : 2.5 h X 126.05 = 315.13 Reparat grup spate : 4 h X 126.05 = 504.20 Demontat/ Montat esapament : 2 h X 126.05 = 252.10 Sudura esapament : 0.5 h X 168.07 = 84.03
