
Reparatii mixer

I.D.: 103710075

Data publicarii	01.10.24	Coduri CPV	50000000-5 50800000-3
-----------------	----------	------------	-----------------------

Pretul estimativ:	8.566,00 RON - 8.566,00 RON
-------------------	-----------------------------

Descriere:	Reparatie mixer- 2,2 kw/1000t- Somcuta- 4.340,00 lei/buc Reparatie mixer- 2,2 kw/1000t- Danesti Somcuta- 4.226,00 lei/buc
------------	--
