
reparatii microbuz MAI 14146

I.D.: 60177620

| | | | |
|-----------------|----------|------------|------------|
| Data publicarii | 19.08.21 | Coduri CPV | 50230000-6 |
|-----------------|----------|------------|------------|

Pretul estimativ: 3.457,98 RON - 3.457,98 RON

Descriere: DIAGNOZA COMPUTERIZATA = 168.07LEI SENZOR TRANSMISIE = 378.15LEI SUPAPA VENTILATIE SECUNDARA = 184.87LEI SENZOR ABS - 2 X 126.05 = 252.10LEI UNITATE COMANDA TRANSMISIE = 1214.29LEI MANOPERA = 1260.50LEI
