
Interventie service la auto SB06YBS

I.D.: 51127724

Data publicarii	29.10.20	Coduri CPV	34320000-6 50100000-6
-----------------	----------	------------	-----------------------

Pretul estimativ:	7.876,35 RON - 7.876,35 RON
-------------------	-----------------------------

Descriere: Diagnoza Demontat remontat chiulasa motor Inlocuit supapa vacuum system turbo Dem rem bara fata Inlocuit set distributie motor Reconditionat chiulasa motor Recalibrat 1 injector Reglat 3 injectoare Inlocuit thermostat sistem racire motor Lustruit faruri Schimb ulei motor si filtru ulei CONFORM DEVIZ 351010
