

## Materiale reparatii camera centrala termica

I.D.: 91125548

Data publicarii 18.12.23 Coduri CPV 44190000-8

Pretul estimativ: 40.960,49 RON - 40.960,49 RON

Descriere: eps ct 80 g20=0.75mc\*231.9328, polifix=15saci\*21.8487,plasa ext 160=100mp\*2.9412, diblu polistiren 70=250\*0.2521, profil pvc cu olasa 2.5m=7\*10.9244, doza 2p 24231=3buc\*2.1008,doza ramificatie 150\*100\*60=1\*3.3613,burghiu sds 10\*160=1\*10.084,plinta smart =10buc\*13.4454,parchet 10mmstejar=20.774\*54.6218,isomaster xps 2cm =31.9\*10.9244,mortar tinci ceradez 25kg=8\*28.1513,trafalet acril 250=1\*22.6891,gratar 265\*285=1\*2.9412pensula 60=2\*5.8824, surub cu diblu 60\*60=100buc\*0.1261,maner telescopic 3m=1\*26.8908, priza dubla zena alb 2\*13.0252, intrerupator dublu zena alb =1\*10.0840, element imbinare smart =4\*2.0168, colt exterior smart =5\*2.0168, terminatie smart =2\*2.0168, disc inox 230\*1.9 =2\*8.4034,folie latime 4m=100\*1.5966, pensula maner lung 90mm=2\*6.3025banda mascare 50\*45=2\*10.084, tenc mozaicata 25kg=5\*268.9076,caparol puzgrund 25kg=2\*243.6975,tv 100\*100\*3=5\*235.2941,electrozi 2.5=4.5kg\*23.5294, electrozi 3.25=4.5kg\*24.3697,disc inox 230\*1.9=3\*8.4034,disc inox 125\*1.2=3\*5.042, ciment =40saci\*24.7899, plasa sudata de 8=6\*357.1429,boltari20\*40\*20=20buc\*5.4622,palet ciment =1\*95lei, tub samota 30=22\*185.2941, invelis beton 30=26\*176.4706,vata minerala 30=52\*30.1092,colector condens 30=1\*815.1261,grilaj ventilatie 30-45=1\*61.1933,usita curatare 12-30=1\*479.2353, coltar placa frontala =4buc\*7.2269, vata minerala 30=2\*30.1681,deflector uni 30=1\*218.4874,racord usita curatare =1\*1002.2521,racord fum30=1\*1069.6387,chit special rapid =10\*63.4454,mortar ptr invelis beton =3\*50, placa