
Servicii reparatie Peugeot 407 CV04PCV

I.D.: 89852477

Data publicarii	21.11.23	Coduri CPV	50112100-4
-----------------	----------	------------	------------

Pretul estimativ: 8.121,27 RON - 8.121,27 RON

Descriere: Reparatie auto conform deviz: Inlocuire senzor ABS stg.fata, reconditinare chiulasa,inlocuire kit distributie+pompa apa, d/r chiualsa + inlocuire tacheti, reparare conexiune furtun spalator parbriz . Total 8121,27+ TVA
