
Servicii de reparatie Uscator rufe Heinner HCD-V804B

I.D.: 95277270

Data publicarii 28.03.24

Coduri CPV

50800000-3

Pretul
estimativ: 309,50 RON - 309,50 RON

Descriere: Servicii de reparatie Uscator rufe Heinner HCD-V804B - inlocuire Filtru scame uscator -
1 buc
