
achizitie servicii de reparatie placa vibratoare

I.D.: 65416963

Data publicarii	21.01.22	Coduri CPV	34913000-0 50000000-5
-----------------	----------	------------	-----------------------

Pretul estimativ: 130,26 RON - 130,26 RON

Descriere: Reparatie placa vibratoare AGT astfel: Curatat carburator 4 T - 1 buc x 67,23 lei bujie NGK BPR6ES - 1 buc x 12,61 lei Honda filtru aer GX 160 - 1 buc x 25,21 lei Honda set garnituri GX 160 - 1 buc x 25,21 lei pentru Strazi conform deviz nr RS 692/17.01.2022 inregistrat cu nr 2015/19.01.2022, referat nr 1700/17.01.2022
