

## Reparatie Dacia Duster

I.D.: 66572831

---

Data publicarii	21.02.22	Coduri CPV	50112000-3
-----------------	----------	------------	------------

---

Pretul estimativ:	1.153,08 RON - 1.153,08 RON
-------------------	-----------------------------

---

Descriere: Reparatie DACIA DUSTER - IS-10-DSP: Demontat cutie de viteze si disc de ambreiaj, inlocuire a simeringului palier, montat disc de ambreiaj si cutie de viteze, completat cu ulei de motor.

---