

---

## Reparatie si revizie autoturism Toyota Hilux

I.D.: 55934176

---

Data publicarii	08.04.21	Coduri CPV	50800000-3 50112200-5
-----------------	----------	------------	-----------------------

---

Pretul estimativ: 3.627,67 RON - 3.627,67 RON

---

Descriere: REVIZIE 1.50 x115.00 2. Carlig remorcare mon - Carlig remorcare 5.50x 115.00 3. 08880-83388 - TOYOTA ULEI PFE 5W30 1L 3.00 x61.26 4. 08880-83389 - TOYOTA ULEI PFE 5W30 5L 1.00x 279.79 5. 90915-YZZJ3 - TOYOTA FILTRU ULEI 1.00x 57.73 6. 90080-43037 - TOYOTA GARNITURA ETANSARE 1.00x 6.59 7. 87139-YZZ33 - TOYOTA FILTRU AER CONDITIONAT 1.00x 87.34 8. PW5D0-0K000 - KIT ELECTRIC 13 PIN 1.00x 1152.19 9. PW960-0K006 - CARLIG REMORCARE 1.00 x1368.88

---